

Bowed out pieces of metal on north side.



View up into wood-framed portion of tower showing framing and efflorescence on planking



Cracked timber beam with partial loss of section



Minor cracking and mortar loss on exterior face of limestone walls



Interior views of limestone walls.

